


latest incident, you can clearly see in this photo how the needle has penetrated the cannula, and the cannula being further back on the needle has folded against the skin surface.



This is an earlier incident. The cannula is folded against the skin, the needle having gone through.

